

Mike Springer <mike@benchmarkls.com>

08:47 (0 minutes ago)

to me, Ken

Hi Jules,

There are three corners out there marked with brass caps, all in T.7S., R29E.,:

N1/4 & NE Cor. Section 7 and the NE Cor. Section 29. That's it. Hope this helps.

Mike Springer, PLS

Benchmark Land Surveying, Inc

217 N. Canyon Blvd.

P.O. Box 476

John Day, Oregon

(541) 575-1251...Work

(541) 620-0676...Mobile